

## **CULVERT AT CALEY GREEN**

### **Reported to Suffolk County Council Highways during 2021 and 2022**

The culvert and ditch at the edge of the green is becoming blocked with vegetation and silt. This ditch carries the rain runoff from A134 and Bear Street drains, plus the perpetual stream that runs from the hill behind the Burial Ground, along the Fairfield boundary and under Bear Street. Lack of regular maintenance is likely to cause blockage and flooding.

Highways Department has now acknowledged ownership by Suffolk County Council. The matter has been passed to Suffolk Drainage Team and is on the list for future maintenance but we have been told that there are other more urgent local priorities.

